




User Guide (v1.0)

USB rechargeable LED head torch 270lm

Please read the following instructions carefully and keep for future reference. Correct usage and maintenance are essential to ensure maximum battery life and performance.

Box Contents:

- 1 x Rechargeable work torch
- 1 x USB charging cable
- 1 x Instruction manual

**CHARGING:**

- 1 Switch the light off before charging
- 2 Plug the USB cable into the USB input an appropriate adapter/power source
- 3 The battery indicator will light up RED and flash during the charging process. When the battery has finished charging it will be a solid RED
- 4 Charging time is approximately 3.5 hours

MAINTENANCE:

- 1 A full charge of at least 5 hours prior to initial use is recommended
- 2 Always recharge after use
- 3 It is advisable to charge the battery if not used for 3 months

CAUTION:

- 1 Never attempt to disassemble the head torch
- 2 Never shine the torch directly in someone's eyes

INSTRUCTIONS FOR USE:

- 1 Press the power button / mode switch to turn the site light ON, the battery indicators will light up
- 2 Further presses of the power button/mode switch will change between modes:
a. Full beam / b. Dimmed mode / c. Red Light > d. COB > COB + Dimmed/ e. COB + Full > f. COB + Dimmed > g. COB + Red Light
- 3 Pressing the power button / mode switch for two seconds will turn the COB light ON and OFF.
- 4 Pressing the sensor button activates the sensor and the light modes can be cycled through by waving a hand in front of the light
- 5 Pressing the sensor button for two seconds will activate the battery indicator.

Rechargeable Head Torch 270Lm

USB Charging

RUNNING TIME	Full beam: 4 hours Dimmed mode: 9 hours Red beam: 6 hours COB light: 9 hours COB + full beam: 135 minutes
CHARGE TIME	3.5 Hours
CHARGE INPUT	5V 1A
7 OPERATION MODES	Full beam > Dimmed mode > Red Light > COB > COB + Dimmed/COB + Red Light
LUMENS	up to 270 lumens
IP LEVEL	IPX4
IK LEVEL	IK05